

## **Marine Paint Manual**

Reference No. 14 - 05 Issue Date: July 2019 (ES)

## NOA A/C II LT

A high build, two-pack epoxy tiecoat anticorrosive designed taking health, safety and environmental issues into consideration. Combined with NOA 10 F LT, the system provides good adhesion to various kinds of antifoulings and finishes (acrylic, epoxy, urethane, etc.) It is overcoatable, allowing unlimited overcoating intervals, in combination with NOA 10 F LT and also for the various kinds of finishes in above water areas.

This paint does not affect the polishing of antifoulings adversely. This tiecoat is applied for all coating systems of outer hull areas. This is the Winter version of NOA A/C II.

Suitable Use Anticorrosive for outer hull (including boottop and topsides), decks,

superstructure, etc.

Type Epoxy (For low temperature use / Two-pack)

Color Gray Gloss Flat

Volume Solids  $65 \pm 2\%$  (ISO3233:1998)

Typical Dry Film Thickness  $50 \sim 125 \,\mu\text{m}$ Approx. Wet Film Thickness  $77 \sim 192 \,\mu\text{m}$ Theoretical Coverage  $8.67 \,\text{m}^2\text{/L} (75 \,\mu\text{m})$ 

Drying Time Surface Dry 2 hours  $(5^{\circ}C)$   $1^{1}/_{2}$  hours  $(10^{\circ}C)$  1 hour  $(20^{\circ}C)$ 

16 hours (5°C) 12 hours (10°C) (20°C) Dry Hard 8 hours Full Cure 7 days (5°C) 6 days (10°C) (20°C) 5 days Interval before Overcoating 16 hours (5°C) 12 hours (10°C) 8 hours (20°C) Min. (20°C) (by self) (5°C) (10°C) Max.

Thinner NIPPON MARINE THINNER 600 (0 ~ 10%, by volume)
Application Method Airless Spray Tip range 0.53 ~ 0.59 mm

Fan angle  $55^{\circ} \sim 69^{\circ}$  (For T/U)  $30^{\circ}$ 

Output pressure 150 ~ 200 kg/cm<sup>2</sup>

Brush / Roller For touching up small areas only

Mixing Ratio by Volume BASE 4 / HARDENER 1

Pot Life after Mixing 2 hours  $(5^{\circ}C)$   $1^{1}/_{2}$  hours  $(10^{\circ}C)$  1 hour  $(20^{\circ}C)$ 

Packaging Two Packs
Japan Local Brand NOA AC II LT

Flash Point BASE 14°C, HARDENER 28°C

Surface Preparation All surfaces to be coated should be clean, dry and free from

contamination.

High pressure fresh water wash and remove all oil / grease, soluble

contaminants and other foreign matters.



## Marine Paint Manual

NOA A/C II LT

Issue Date: July 2019 (ES)

Safety

Take precautions to avoid skin and eye contact (i.e. gloves, goggles, face masks, barrier creams etc.)

Proper ventilation and protective measures must be provided during applications and drying period to keep solvent vapor concentrations within safe limits.

Prior to use, obtain, consult and follow the SDS for this product

concerning health and safety information.

## < Note >

- 1) The information contained in this sheet is liable to modification from time to time in the light of experience and our policy of continuous product development.
- 2) Prior to overcoating, remove heavily chalked layer, salt contamination, etc. by fresh water washing.
- 3) For availability of product consult Nippon Paint Marine representatives.
- 4) Unit size and filled volumes can vary due to local regulations.
- 5) Store the paints in paint store.